General Environmental Incident Summary

Incident: 3365 Date/Time Notice: 6/25/2014 0945 DEM Incident No:

Responsible Party: Cypress Energy Partners

Date Incident: 6/20/2014 Time Incident: 0748 Duration: 2 minutes

County: McKenzie Twp: 150 Rng: 100 Sec: 13 Qtr: SE SE

Lat: 47.80752 Long: -103.41480 Method: Interpolation from map

Location Description: SBG Arnegard Facility (aka Alati Arnegard SWD)

Submitted By: Jeff English Affiliation: VP-Operations

Address: 5727 South Lewis Avenue

Suite 500

City: Tulsa State: OK Zip: 74105

Received By:

Contact Person: Jeff English

5727 South Lewis Avenue

Suite 500

Tulsa, OK 74105

Distance Nearest Occupied Building: Release Contained: Yes

Type of Incident: Pump Leak

Description of Released Contaminant: Produced Brine Water

Volume Spilled: 10.00 barrels Ag Related: No EPA Extremely Hazardous Substance: No Reported to NRC: No

Cause of Incident:

Water hauler disconnected hose from offload lane while it was still under pressure and caused produced brine water to spill off of truck until the pump was turned off.

Risk Evaluation:

There were no immediate risks as a result of this spill.

of Fatalities: # of Injuries: Affected Medium: 03 - soil

Potential Environmental Impacts:

The spill was contained on our pad site location and did not drain anywhere off of the pad site. All contaminated materials were collected and disposed of properly.

Action Taken or Planned:

Majority of the liquid was captured at the concrete offload lane and it was sucked back up by the water hauler. There was approximately a 10' area off of the concrete offload lane that had produced brine water on the surface area and we used our spill kit dipers to contain this liquid. We used a bobcat to scrape the dirt and it was hauled off for disposal by Black Shirt Trucking to Indian Hills Disposal. We replaced the area with fresh scoria.

Monday, July 21, 2014 Page 1 of 2

Wastes Disposal Location: Black Shirt Trucking hauled the material off to Indian Hills Disposal.

Agencies Involved:

Updates

Date: 7/7/2014 Status: Reviewed; O&G Lead Staff: Roberts, Kris

Updated Volume:

Notes:

Release, due to an on-location pump leak, remained on location according to the report. NDIC retains oversight. Forwarded to NDIC.

Monday, July 21, 2014 Page 2 of 2